NFORMATION REPORT INFORMATION This material contains information affecting OENTRAL INTELLIGENCE AGENCY the meaning of the Espicinage Laws, Title 18. U.S.C. Secs. 793 and 794, the transmission or revolation of which in any manner to an unauthorized person is prohibited by law. **13** SEP C-O-N-F-I-D-E-N-T-I-A-L COUNTRY Nigeria REPORT NO 25X1 **SUBJECT** Niger River Dam and DATE DISTR. 15 September 1967 Hydroelectric Project 25X1 NO. PAGES REFERENCES 11 August 1967 DATE OF INFO. AREA INDEXED PLACE & DATE ACQ THIS IS UNEVALUATED INFORMATION SOURCE The Document and Pictorial Services Division, Central Reference Service, has recently accessioned 22 ground and aerial photographs and two personality photographs showing construction progress on the Niger River Dam and Hydroelectric Plant. Copies of the photographs described below may be obtained by citing the CIA numbers listed. 1204616 Aerial view of New Bussa with the Niger River in the background. New Bussa is an extensive housing project being built to house the population of the old town of Bussa which will be flooded out by the new lake when the Niger Dam is completed. 1204617 Aerial view of New Bussa showing close-up of new mosque. 1204618 Aerial view of Niger Dam at Kainji from upstream (lake) side. Former Kainji Island is in the center with right channel of the Niger dammed off in right foreground and all the Niger River flowing down left channel and through spillway in dam. 1204619 Aerial view of Niger Dam looking downstream (Southeast). Trees on the former Kainji Island in foreground have not yet been cut, but the whole area will eventually be cleared to form the bottom of the new Kainji Lake. 1204620 Aerial view of Niger Dam looking downstream. On the left bank the left rock-fill wing wall of the dam has been built up to connect with cement center section; on the right bank the right rock-fill wing wall shows on the right of the photograph but has not yet been connected to the cement center section. 1204621 Aerial view of Niger Dam looking downstream, showing partially completed left rock-fill wing wall extending between completed cement center section and upper navigation lock which is being built in the middle distance just left of center. Beyond the locks on the downstream side, a passing basin for barge traffic has been par-

INFORMATION REPORT INFORMATION REPORT

tially excavated.

U C-O-N-F-I-D-E-N-T-I-A-L

25X1

25X1

gerfernischien geropresing gest gerfernischien declernischien 5

The dissemination of this document is limited to civilian employees and active duty military personnel within the intelligence components of the USIB member agencies, and to those senior officials of the member agencies who must act upon the information. However, unless specifically confolled in accordance with paragraph 8 of DCID 1/7, it may be released to those components of the departments and agencies of the U. S. Government diffectly participating in the production of National Intelligence. IT SHALL NOT BE DISSEMINATED TO CONTRACTORS. It shall not be disseminated to organizations or personnel, including consultants, under a contractual relationship to the U. S. Government without the written permission of the originator.

25X1

1204622 - Niger Dam looking downstream. Cement center section completed except for installation of spillway gates and intake gate for penstocks. Openings for penstocks leading to turbines clearly visible at bottom of cement center portion; two penstocks serve each turbine and generator. Eventual installation will be twelve turbine-generator sets: eight discharging into left channel and four into right channel. Right end of cement section is not yet connected to right rock-fill wing wall, since work is still in progress in dammed-off right channel of Niger River.


Breakwater in the river below the dam is almost completed to

1204623- Aerial view of upper locks looking upstream (Northwest). The left rock-fill wing wall shows at the left of the photograph. The excavation in the foreground is passing basin for barges and other river vessels.

provide protected entrance to lower navigation lock.

- Aerial view of the Niger Dam looking upstream (Northwest). The entire current of the Niger River is passing through the spill-way at the right front of the photograph. At right of the photograph, is the left rock-fill wing wall connected to cement center portion but not yet built up to full height. New permanent bridge over the Niger shows in the left foreground. Right rock-fill wing wall mostly completed beyond bridge, but not yet connected to cement center portion.
- 1204625 -Close-up aerial view of the Niger Dam looking upstream. Outline of former Kainji Island is clearly visible with entire Niger flowing through left channel and spillway which is at the right of the photograph. Dammed off right channel of the Niger shows at the left with upstream cofferdam in the upper left of the photograph. Cement center section of the dam completed, with power house for four initial generators almost completed halfway across the dam face. This part of the power house will contain two turbine-generators discharging into the left channel, two more discharging into the right channel and two sets of penstocks whose turbine will also discharge into the right channel of the Niger when installed later. The rest of the power house across the remaining portion of the dam face is not under construction at this time. It will cover the final six turbinegenerators for which penstocks are already built into the dam.
- 1204626 Oblique aerial view of the concrete center section of the Niger Dam looking upstream showing the almost completed portion of the power house, administration building in front of it and work in progress preparing the tailrace for the four turbine-generator sets which will eventually discharge into the right channel of the Niger (center foreground).
- 1204627 Enfilade view of Niger Dam showing successively from foreground:
 work in progress in bed of dammed-off right channel of the Niger
 River; tailrace being prepared to discharge into right channel;
 concrete center section with power house and administrative
 building; left channel flowing through spillway with new permanent bridge spanning it at right of photograph; left rockfill wing wall almost completed back to upper lock in midground.

5 4 C-O-N-F-I-D-E-N-T-I-A-L



- 1204629 Aerial view of the fishhook bend in the Niger River at Awuru looking upstream. The navigation canal being constructed across the neck of the bend on the right bank does not show, but its downstream entrance is just outside the left edge of the photograph and the canal will run roughly parallel to the small highwater season channel shown in the photo cutting across the neck.
- 1204630 Aerial view of the navigation canal by-passing Awuru Rapids. Downstram entrance to the canal is in the foreground, lock is in the center and the upstream entrance is in the far background.
- 1204631 Aerial view of the lock being built in Awuru Rapids by-pass canal. The Niger River is shown in the background flowing down to the fishhook bend just outside the upper right corner of the photograph. The ends of the lock have been finished and gates installed but the sides not yet begun.
- 1204632 Aerial view of the lock in Awuru Rapids by-pass canal showing the Niger River below the fishhook bend flowing towards the lower end of the canal just outside the lower right corner of the photograph.
- 1204633 The upper entrance to the Awuru Rapids by-pass canal showing the weir across the river partially over-topped by the Niger River at flood season.
- 1204634 The excavated pit in which the lower navigation lock is being constructed, looking upstream.
- 1204635 Juncture of the future tailrace and dammed-off right channel of the Niger River showing the cement center section of the dam and the partially completed power house and the administration building. The large square gantry crane on top of the dam will travel back and forth and be used to open and close intake gates for penstocks. The drag lines on top of the dam at both ends are being used for construction purposes and will be removed upon completion of the dam.
- 1204636 Close-up of the power house entrance and the partially completed administration building with central concrete section of the Niger Dam looming over the top of the power house.

 Actual size of the dam can be judged by the people standing on the top.
- 1204637 Close-up of the downstream face of the Niger Dam showing from right to left: the left rock-fill wing wall of the dam being built on to the cement center portion; the framework of the spillway, gates to which are not yet installed; the discharge openings for the turbine-generator sets showing at the bottom of the foundations for future part of the power house to be built at a later date. The large square gantry crane for raising and lowering intake gates has been installed on the top of the dam (center).


2	ᄃ	v	1
_	J	Л	


Next 4 Page(s) In Document Exempt

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Power house & admin. bldg. 11 August 1967.

Confidential (17,29) CIA 1204636

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0





STAT


NIGER DAM, NIGERIA, AUGUST 11, 1967.

Close up of power house entrance and partially completed administration builded 2004/05/25 CARRIDA/8-045/46A8623090400070 of Niger Dam looming over top of power house. Actual size of dam can be judged by people standing on top.

NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E

New town of New Bussa u/c to house population of old Bussa which will be flooded by Niger Dam lake. 11 August 1967.

Confidential (6,7,10) CIA 1204616



NIGER DAM, NIGERIA, AUGUST 11, 1967.


1. View of New Bussa from the air with Niger River in backgrapproved New Release 2004/03/26neW-EDR38-94546A9983009109071Ag built
to house population of Bussa, ancient town which will be
flooded out by new lake when Niger Dam is finished.

STAT

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam u/c 1kg from upstream (1ake) side. 11 August 1967.

Confidential (17,29) CIA 1204618




STAT

NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E

New Bussa. Mosque center. 11 August 1967.

Confidential (6,7,10) CIA 1204617



Approved For Release 2004/03/26: CIA-RDP78-04546A00330001000770 11, 1967.

NIGER DAM, NIGERIA, AUGUST 11, 1967.

New Bussa showing close-up of New Mosque.

Approved For Release 2004/03/26: CIA-RDP78-04546A003300010007-0

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam u/c 1kg downstream. 11 August 1967.

Confidential (17,29)

CIA 1204621




STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

6. Aerial view of Niger Dam looking downstream, showing partially completed left rock-fill wing wall extending between completed cement center section and upper naviga-typeroved for Release 1200 at 125 LIA RDF 125 A 125

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg downstream. 11 August 1967.
Confidentia1 (17,29) CIA 1204620

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0




STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

5. Aerial view of Niger Dam looking downstream. On left bank left rock-fill wing wall of dam has been built up to Approved For Release 2004/03/26 rcy4-gpp78-04546A003860046027-9ight rock-fill wing wall shows on right of picture but has not yet been connected to cement center section

NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c 1kg SE downstream. 11 August 1967. 67. Confidential (17,29)

CIA 1204619




STAT

Aerial view of Niger Dam looking downstream (Southeast).

Trees on Form Belease 2004/03/26 not ARDP 38-26548400388004000740 yet been cut but whole area will eventually be cleared to form bottom of new Kainji Lake.

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0 NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c 1kg downstream. 11 August 1967. Confidential (17,29)



STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

7. Closer view of Niger Dam, looking downstream. Cement center section completed except for installation of spill-way gates, intake gates for penstocks. Openings for penstocks leading to turbines clearly visible at bottom of cement center portion, two penstocks serve each turbine and generator. Eventual installation will be 12 turbine-generator sets: 8 discharging into left channel and 4 into right channel. Right end of cement section not yet connected to right rock-fill wing wall, since work still in programmed for the programmed of the programm

NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c. Upper locks 1kg NW upstream. 11 August 1967. 25X1 (17,29)

Confidential

CIA 1204623



STAT

NIGER DAM, NIGERIA,


AUGUST 11, 1967

8. Aerial view of upper locks looking upstream (Northwest). Left rockfill wing wall shows at left of Approved For Release 2004/03/26a CIA-RDP 8,04546A003300010007-0

is passing basin for barges and other river vessels.

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg NW upstream. 11 Aug 1967.
Confidential (17,29) CIA 1204624

Approved For Release 2004/03/26: CIA-RDP78-04546A003300010007-0



STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.


Aerial view of Niger Dam looking upstream (Northwest).

Entire current of Niger River passing through spillway at right front of picture. At right of picture left rock-fill wing wall connected to cement center portion but not yet built up to full height. New permanent builded over Niger shapproved fer selease 2004/03/26: Charles Frock-fill wing wall mostly completed beyond bridge, but not yet connected to cement center portion.

Approved For Release 2004/03/26: CIA-RDP78-04546A003300010007-0

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg upstream. 11 Aug 1967.

Confidential (17,29) CIA 1204625



STAT

10.

Close-up aerial view of Niger Dam looking upstream. line of former Kainji Island clearly wisible with entire Niger flowing through left channel and spillway which at right of picture. Dammed off right channel of Niger shows at left with upstream cofferdam in upper left of picture. Cement center section of dam completed, with power house for four initial generators almost completed halfway across This part of power house will contain two turbine-generators discharging into left channel, two more discharging into right channel and two sets of penstocks whose turbines will also discharge into right channel of Niger when installed later. Hest of power house across remaining portion of dam face not being constructed at this Approved For Release 2004603/26:eCRIRDP78-04546A003300010007-0 which penstocks already built into dam.

25X1

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg upstream at almost completed portion of power house. 11 August 1967.
Confidential (17,29) CIA 1204626



STAT


NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c. 11 August 1967.
Confidential (17,29)
CIA 1204627

STAT

NIGER DAM, NIGERIA, AUGUST II, 1707.

Enfilade view of Niger Dam showing successively from foreground; work in progress in bed of dammed-off right channel
ground; work in progress in bed of dammed-off right channel
of Niger River; tailrace being prepared to discharge into
of Niger River; tailrace being prepared to discharge into
right channel; cemorate center section with power house
right channel; cemorate center section with power house
of Niger River; tailrace being prepared to discharge into
approved Function of the control of the con

```
NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E
Lkg NW upstream at Awuru Rapids in Niger River 11mi. below Niger Dam u/c.
11 August 1967.
Confidential (1,17,29) CIA 1204628
```



STAT |

13.

Aerial view looking upstream (Northwest) showing Awuru Rapids in Niger River 11 miles below Niger Dam at Kainji. These rapids will be by-passed by a short navigation canal across neck of sharp fishhook bend on far (right) bank. Weir to divert water into upstream entrance of canal shows Weir To Gar Redease 2004/03/26: CIA-RDP78-04546A003300010007-0

NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E Fishhook bend in Niger River at Awuru 1kg upstream near Niger Dam u/c. 11 August 1967. Confidential (1,17,29)



STAT


NIGER DAM, NIGERIA, AUGUST 11, 1967.

Aerial view of fishhook bend in Niger River at Awuru looking upstream. Navigation canal being constructed across neck of bend on right bank does not show, but its downstream entrance bend on right bank does not show, but its downstream entrance is just outside left edge of picture and canal will run is just outside left edge of picture season channel shown in roughly paragraphic across neck ppresent this picture cutting across neck ppresent the picture cutting across neck present the picture across neck present the

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam Navigation canal by-passing Awuru Rapids. 11 Aug 1967.

Confidential (17,29) CIA 1204630



STAT

15.

NIGER DAM, NIGERIA. AUGUST 11 1967.

Aeria/pproved Per Relatice 2004/03/26 a GIA-RD Pras 04546 A0033000 10007-0

Downstream entrance to canal in foreground, lock in center and upstream entrance in far background.

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam Project. Lock in Awuru Rapids by-pass canal u/c. 11 Aug
1967.
Confidential (17,29)
CIA 1204631



STAT

16.

NIGER DAM, NIGERIA, AUGUST 11, 1967.

Aerial view of lock being built in Awuru Rapids by-pass canal. Niger River shown in background flowing down to fApproved For Release 2004/03/26 CIAPPP 78:04546A9933990 5000Fib ture. Ends of lock have been finished and gates installed but sides not yet begun.

25X1

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Lock in Awuru Rapids by-pass canal. 11 Aug 1967.

Confidential (17,29) CIA 1204632




Approved For Release 2004/03/26: GJARDP 789045468063300016009-01 ng
Aerial view of lock
Niger River below fishhook bend flowing towards lower end
Niger River below fishhook bend flowing towards lower end
of annal just outside lower right corner of picture.

STAT

17.

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Upper entrance to Awuru Rapids by-pass canal.
11 August 1967.
Confidential (17,29) CIA 1204633



STAT


NIGHT DAM, NIGERIA, AUGUST 11, 1967.

18. Upper entrance to Awuru Rapids by-pass canal showing weir a special for Relaast 2014/93/26 a file-Representation of the following weights a special for Relaast 2014/93/26 a file-Representation of the file-Representation of

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam. Excavated pit in which lower navigation lock is u/c
lkg upstream. 11 August 1967.

(17)

CIA 1204634




21.

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam u/c. 11 August 1967.

Confidential (17,29)

CIA 1204635



STAT

22.

Juncture of future tailrace and dammed off right channel of Niger River showing cement center section of dam and of Niger River showing cement center section of dam and partially completed power house and administration building. Large square gantry crane on top of dam will traveling. Large square gantry crane on top of dam will travel back and forth and be used to open and close intake gates back and forth and be used to open and close intake gates for Approved for Release 1004/03/26n: GM-RDPFS-04546A003300010007-0 upon completion of dam.


NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c: Downstream face of dam. 11 August 1967.

25X1 Confidential

(17,29)

CIA 1204637

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0



STAT

24.

NICER DAM, NIGERIA, AUGUST 11, 1967.

Close-up of downstream face of Niger Dam showing from right to left: left rock-fill wind wall of dam being built on to cement center portion; framework of spillway, gates to which not yet installed; discharge openings for turbine-generator sets showing at bottom of foundations for Turing parties belower noise IAFBDER-04546A00239001000701te.

Large square gantry crane for raising and lowering intake rates has been installed on top of dam (center).